Inspection Tips / MDEQ Panel Discussion

- 1. Conduct a thorough Review of your facility to identify:
 - Wastewater streams, and the destination of the wastewater
 - Waste streams (solid waste, liquid industrial waste, hazardous waste)
 - Processes that emit air contaminants
- 2. Know Your Permit! Understand requirements.
- 3. Establish Procedures
 - Monitoring procedures
 - Recordkeeping practices
 - Reporting schedules
 - Internal review process
- 4. Practice Good Record Keeping!
 - Keep them organized
 - Develop a retention schedule per requirement
- 5. Know the Reporting Deadlines (Don't miss reporting deadlines)
- 6. Don't Recreate Records or falsify data.
- 7. Take immediate action to correct violations. Don't wait until you get caught!
- 8. Do not ignore correspondence from the DEQ.
- 9. Communicate with your Inspector(s)
 - Ask for a business card when they visit
 - Ask questions
- 10. Educate Yourself
 - Understand Terminology
 - Read MDEQ Education materials
 - Attend MDEQ Workshops
 - Keep up on Rules

